

L 106

Present Name <i>Clis Branson</i>	County <i>Fulton</i>	Classification <i>Local</i>	Index Number
Address of Mine <i>Spava RR 3</i>	Mine Number	Trade Name	
Changes of Name:			

Railroads & Highways Serving Mine

Date Mine Opened	Seam	Thickness	Depth	Type of Opening	Mining Plan	Mining Method	Haulage	Hoisting	Loading	Lights	Special Preparation Plant
<i>1928</i>	<i>4</i>	<i>4 ft</i>		<i>Drift</i>	<i>R-P</i>	<i>Hand</i>	<i>Hand</i>	<i>Horse</i>	<i>Hand</i>	<i>open</i>	<i>Port Coal</i>

*****COAL PRODUCTION*****

Total Production to 1936 Inclusive	1937	1938	1939	1940	1941	1942	1943	1944
		<i>187</i>	<i>52</i>					

Dec 5-38

REMARKS *An old Drift. Pulling Pillars called Aug 4-1939 mine abandoned April-1939*