

No. 14.—June 24, 1884. Nicholas Gardner and Mathias Issler, were severely hurt at Schureman mine by falling roof. While running a machine, Gardner's left arm was badly cut, and Issler had his leg broken.

No. 15.—October 24, 1883. John Kingham, employed as shoveler for machine at William Skellet's mine, had his leg broken, by a collision of pit cars on one of which he was riding.

No. 16.—January 12, 1884. At Skellet mine, John Kummick was seriously injured, by slate falling on him, while loading a car with coal. His ribs were crushed into the lungs. The doctors say he cannot live.

No. 17.—September 29, 1883. James Smith was badly bruised on head and shoulders by falling slate, while working with a machine at Skellet mine.

No. 18.—December 6, 1883. At Coulterville mines, by an explosion of gas, six men were seriously burned. James W. Sively had his clothes entirely burned off. John Malarn about his face and back. James Frior, face, neck and right hand. Frank Horn, face, back and arms. W. S. Reid, face and hands, John Orr, face, neck, arms and back.

No. 19.—March 11, 1884. Richard Beaty, driver at tunnel No. 7, was caught between the cars and bruised; he was idle one week.

No. 20.—March 20, 1884. At St. Louis Ore and Steel Co. mine, Forest Minnewell, while driving, was hurt by falling timber, knocked out by car jumping the track.

No. 21.—Watt. Bickton had his head cut and back hurt, by coal from a blast fired before he had time to get away.

No. 22.—November 14, 1883. Morgan Davis, was severely bruised at Providence Coal Co. mine, by the fall of coal he was undermining.

No. 23.—October 2, 1883. At A. Brandenberger & Co.'s mine, George Platt, had his arm broken by not going far enough away while firing a blast.

No. 24.—June 20, 1884. Frank Kamer had his back injured at John Kloes mine, by falling slate which he had tried to take down a short time before.

No. 25.—October 20, 1883. Anthony Faber was severely burned by the explosion of about two-thirds of a keg of powder, at Gilliwick and Richards mine.

No. 26.—May 17, 1884. At Hazard and Emory's mine, Charles Emory, Supt. In repairing escapement shaft, timber fell, striking him on the head; he was idle one week.

No. 27.—April 20, 1884. John Gardiner had his left leg broken by the bucket becoming detached and falling back on him, in a shaft which was being sunk by Pittsburgh Mining Co. at Belleville.

No. 28.—September 10, 1883. At Victor mine, Joseph Worms was hurt on his back by coal from a blast he had fired, and went back to examine.

No. 29. November 23, 1883. William Lewellin received a severe injury, at Victor mine, by coal from a blast striking him on his head.

No. 30.—April 10, 1884. While Joseph Worms was taking down top coal at Victor mine, slate fell on him bruising his back.

No. 31.—September 14, 1883. Henry Lenz was hurt by cage coming down on him, while passing through the bottom of shaft at C. Reinicke's mine.

No. 32.—September 12, 1883. At C. Reinicke's mine No. 1, Bennet Kelner was hurt while loading a car.

No. 33.—October 11, 1883. Charles Reibling was severely hurt on his left side and leg, by loose coal falling on him, while shoveling for a machine, at C. Reinicke's mine.

No. 34.—March 14, 1884. At C. Reinicke mine, Victor Schendlin received a bruise on his back and arm by falling slate, while filling box of water.

No. 35.—January 14, 1884. Henry Markstorm was burned on his face, arms and breast, by igniting powder in a hole that had become clogged in charging, and which he was trying to force back. Idle two months.

No. 36.—May 17, 1884. While Adam Kunkle was shoveling for a machine at C. Reinicke's mine, about four or five bushels of coal fell on him, injuring him internally.

No. 37.—March 28, 1884. James Conroy was severely burned on his face, breast and arms, by the explosion of powder in a standing shot which he was drilling out at J. Taylor's mine, the blast of coal tearing the flesh from his right arm.

No. 38.—June 7, 1884. Joseph Bodaker was bruised on his side and abdomen by falling of roof between the props, at J. Taylor's shaft.