

;

SANGAMON ct^y
T16N R5W
Sec 15 SWSESW

Mine in Chapel Coal
MI 2593

Sangamon County
T16N R5W
Sec. 15 SWSESW

Mine voids in Chapel Coal encountered in boreholes at this location. In nearby holes the seam was 2-3 feet thick. Presumably this was a small drift mine.

See p. 14. of *Drilling Rept:*
Subsurface investigation for Proposed
Dept. of Ag Building
State Fairgrounds
Springfield, IL "

for: Loewenberg & Loewenberg
120 S. La Salle Street
Chicago, IL 60603

by: Soil Testing Services, Inc.
111 Pfingston Road
Northbrook, IL 60062
STS Job No. 18623

January 1977
Communication from Bob Bauer to
Colin Treworgy, July 1991

Notes:

Depth to coal 205' to 210' (No. 8. coal)
Some borings encountered an upper
seam believed to have been
locally mined. (see Report)

MI 2593 -

5W

16N



— SITE PLAN —

SPRINGFIELD — ILLINOIS

1977

SANGAMON Cty



SOIL TESTING SERVICES

111 PFINGSTEN ROAD

NORTHBROOK ILLINOIS

JAN. 1977 18